

---

**Audel™**

**Machine Shop Tools  
and Operations  
All New 5th Edition**



---

**Audel™**

**Machine Shop Tools  
and Operations**

**All New 5th Edition**

**Rex Miller**  
**Mark Richard Miller**



WILEY

Wiley Publishing, Inc.

---

Vice President and Executive Group Publisher: Richard Swadley  
Vice President and Executive Publisher: Robert Ipsen  
Vice President and Publisher: Joseph B. Wikert  
Executive Editorial Director: Mary Bednarek  
Editorial Manager: Kathryn A. Malm  
Executive Editor: Carol A. Long  
Senior Production Editor: Fred Bernardi  
Development Editor: Kevin Shafer  
Production Editor: Pamela M. Hanley  
Text Design & Composition: TechBooks, Inc.

Copyright © 2004 by Wiley Publishing, Inc. All rights reserved.  
Copyright © 1965, 1970, and 1978 by Howard W. Sams & Co., Inc.  
Copyright © 1983 by The Bobbs-Merrill Co., Inc.

Published simultaneously in Canada

No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, scanning, or otherwise, except as permitted under Section 107 or 108 of the 1976 United States Copyright Act, without either the prior written permission of the Publisher, or authorization through payment of the appropriate per-copy fee to the Copyright Clearance Center, Inc., 222 Rosewood Drive, Danvers, MA 01923, (978) 750-8400, fax (978) 646-8700. Requests to the Publisher for permission should be addressed to the Legal Department, Wiley Publishing, Inc., 10475 Crosspoint Blvd., Indianapolis, IN 46256, (317) 572-3447, fax (317) 572-4447, E-mail: permcoordinator@wiley.com.

**Limit of Liability/Disclaimer of Warranty:** While the publisher and author have used their best efforts in preparing this book, they make no representations or warranties with respect to the accuracy or completeness of the contents of this book and specifically disclaim any implied warranties of merchantability or fitness for a particular purpose. No warranty may be created or extended by sales representatives or written sales materials. The advice and strategies contained herein may not be suitable for your situation. You should consult with a professional where appropriate. Neither the publisher nor author shall be liable for any loss of profit or any other commercial damages, including but not limited to special, incidental, consequential, or other damages.

For general information on our other products and services, please contact our Customer Care Department within the United States at (800) 762-2974, outside the United States at (317) 572-3993, or fax (317) 572-4002.

**Trademarks:** Wiley, the Wiley Publishing logo, Audel, and related trade dress are trademarks or registered trademarks of John Wiley & Sons, Inc. and/or its affiliates in the United States and other countries, and may not be used without written permission. All other trademarks are the property of their respective owners. Wiley Publishing, Inc., is not associated with any product or vendor mentioned in this book.

Wiley also publishes its books in a variety of electronic formats. Some content that appears in print may not be available in electronic books.

*Library of Congress Cataloging-in-Publication Data:*

eISBN: 0-764-56861-2

Printed in the United States of America

10 9 8 7 6 5 4 3 2 1

---

# Contents

---

Acknowledgments	vii
About the Authors	ix
Introduction	xi
Chapter 1: Power Hacksaws, Power Band Saws, and Circular Saws	1
Chapter 2: Basic Machine Tool Operations	25
Chapter 3: Drilling Machines	39
Chapter 4: Drilling Machine Operations	51
Chapter 5: Vertical Boring Mills and Horizontal Boring Machines	83
Chapter 6: Lathes	107
Chapter 7: Lathe Operations	135
Chapter 8: Cutting Screw Threads on the Lathe	167
Chapter 9: Lathe Attachments	195
Chapter 10: Turret Lathes	209
Chapter 11: Milling Machines	233
Chapter 12: Milling Machine Operations	241
Chapter 13: Milling Machine Dividing Heads	267
Chapter 14: Indexing Operation	281
Chapter 15: Shapers	301

Chapter 16: Planers	325
Chapter 17: Slotters	341
Chapter 18: Abrasive Metal Finishing Machines	353
Chapter 19: Electroforming	365
Chapter 20: Ultrasonics in Metalworking	379
Chapter 21: Machine Shop Robotics and Electronics	389
Appendix	405
Index	427

---

# Acknowledgments

---

A number of companies have been responsible for furnishing illustrative materials and procedures used in this book. At this time, the authors and publisher would like to thank them for their contributions. Some of the drawings and photographs have been furnished by the authors. Any illustration furnished by a company is duly noted in the caption.

The authors would like to thank everyone involved for his or her contributions. Some of the firms that supplied technical information and illustrations are listed below:

Alcoa  
Aluminum Co. of America  
Armstrong-Blum Mfg. Co.  
Atlas Press Co.  
Buffalo Forge  
Bullard Co.  
Cincinnati Milacron Co.  
Ex-Cell-O Corp.  
Fred V. Fowler Co.  
Giddings and Lewis Machine Tool Co.  
Gisholt Machine Co.  
Gulton Industries  
Hardinge Brothers, Inc.  
Heald Machine Co.  
Henry G. Thompson Co.  
Jacobs Manufacturing Co.  
Kalamazoo Saw Div. KTS Industries  
Lufkin Rule Co.  
Machinery's Handbook, The Industrial Press  
Monarch Cortland  
Morse Twist Drill and Machine Co.  
National Drill and Tool Co.  
Nicholson File Company  
Norton

---

**viii** Acknowledgments

Prab Robots

Raytheon

Rockwell Manufacturing

Royal Products

South Bend Lathe, Inc.

Startrite, Inc.

Ultimation

Wilton Tool Manufacturing Co., Inc.



---

## About the Authors

---

**Rex Miller** was a Professor of Industrial Technology at The State University of New York—College at Buffalo for over 35 years. He has taught on the technical school, high school, and college level for well over 40 years. He is the author or coauthor of over 100 textbooks ranging from electronics to carpentry and sheet metal work. He has contributed more than 50 magazine articles over the years to technical publications. He is also the author of seven Civil War regimental histories.

**Mark Richard Miller** finished his B.S. degree in New York and moved on to Ball State University where he obtained the master's and went to work in San Antonio. He taught in high school and went to graduate school in College Station, Texas, finishing the doctorate. He took a position at Texas A&M University in Kingsville, Texas, where he now teaches in the Industrial Technology Department as a Professor and Department Chairman. He has coauthored seven books and contributed many articles to technical magazines. His hobbies include refinishing a 1970 Plymouth Super Bird and a 1971 Roadrunner. He is also interested in playing guitar, which he did while in college as lead in The Rude Boys band.



---

# Introduction

---

The purpose of this book is to provide a better understanding of the fundamental principles of machine shop practices and operations for those persons desiring to become machinists. The beginning student or machine operator cannot make adequate progress in his or her trade until he or she possesses a knowledge of the basic principles involved in the proper use of various tools and machines commonly found in the machine shop.

One of the chief objectives has been to make the book clear and understandable to both students and workers. The illustrations have been selected to present the how-to-do-it phase of many of the machine shop operations. The material presented here should be helpful to the machine shop instructor, as well as to the individual student or worker who desires to improve himself or herself in this trade.

The proper use of machines and the safety rules for using them have been stressed throughout the book. Basic principles of setting the cutting tools and cutters are dealt with thoroughly, and recommended methods of mounting the work in the machines are profusely illustrated. The role of numerically controlled machines is covered in detail with emphasis upon the various types of machine shop operations that can be performed by them.

This book is presented at a time when there is a definite trend toward expanded opportunities for vocational training of young adults. An individual who is ambitious enough to want to perfect himself or herself in the machinist trade will find the material presented in an easy-to-understand manner, whether studying alone or as an apprentice working under close supervision on the job.



---

# Chapter I


## Power Hacksaws, Power Band Saws, and Circular Saws

---

Power hacksaws, power band saws, and circular saws are very important to machine shop operations. A large number of power hacksaws and power band saws are in use in the metalworking industry.

### Power Hacksaws

A power hacksaw is an essential machine in most machine shop operations. For many years a hand-operated hacksaw was the only means for sawing off metal. Power-driven machines for driving metal-cutting saw blades have been developed to make the task easier. The power hacksaw can do the work much more rapidly and accurately. The machinist should be familiar with these machines, the blades used on the machines, and the operations performed on them. One type of power hacksaw commonly found in machine shops is shown in Figure 1-1.



**Figure 1-1** Power hacksaw.

### Basic Construction

Power hacksaws are designed to make the sawing of metal a mechanical operation. The stock is usually held in a vise mounted on the base of the machine. An electric motor is used to supply power for the machine.

### **Drive Mechanism**

The drive shaft is connected by a V-belt and gears to the electric motor mounted on the machine. The drive mechanism is shielded by guards for safety in operation.

### **Frame**

A U-shaped frame is used on the smaller power hacksaws to support the two ends of the saw blade, which is under tension. The heavier machines use a four-sided frame and a thin backing plate for the blade of the saw.

### **Worktable and Vise**

Most worktables are equipped with a vise that can be mounted either straight or angular to the blade. The worktable is usually mounted on a ruggedly constructed base. Many worktables are provided with T-slots for the purpose of supporting special clamping devices.

### **Special Features**

Nearly all power hacksaws raise the blade on the return stroke. This feature prevents dulling of the blade by dragging it over the work as the blade is returned to the starting position.

Another important feature is a blade safety switch that automatically stops the machine if the blade should break during operation of the saw. The safety switch prevents any damage that could result if the machine continued operation with a broken blade.

### **Coolant System**

Some power hacksaws are equipped with a coolant system that delivers a coolant to the hacksaw blade. The coolant passes from a receiving tank to a pump and then to the work. The machine is equipped with a trough to catch the coolant, which may be screened to remove any chips of metal.

### **Saw Capacity**

Small power hacksaws can be used on square or round stock ranging from  $\frac{1}{8}$  inch to 3 inches. The larger machines have a capacity ranging to 12 inches (square or round), or even larger.

The capacity of a machine for angular cuts is different from its capacity for straight cuts. The cutting surface is longer for angular cutting. Thus, the saw must be equipped not only with a swivel vise but also with a long enough stroke to make the angular cut.

### **Blades**

High-speed tungsten steel and high-speed molybdenum steel are the most commonly used materials in power saw blades. If only the teeth are hardened, the blades are called *flexible blades*.

Power hacksaw blades are ordered by specifying length and width, thickness, and teeth per inch. For example, they are available in 12" × 1" length and width at 0.050-inch thickness. The teeth per inch (TPI) would be either 10 or 14. The 14" × 1" × 0.050" blade is available in only 14 TPI. Blades also come in 17" × 1" with a thickness of 0.050 inch and either 10 or 14 TPI. Blades with a thickness of 62 thousandths of an inch (0.062 inch) are usually 1¼ inches wide.

High-speed, shatterproof blades are designed to meet safety and performance requirements. The high-speed molybdenum blades are longer wearing and give the best results for general use. They, too, come in 12-inch, 14-inch, and 17-inch lengths with a 1-inch or 1¼-inch width. These blades are made in both 10 and 14 TPI sizes. Thickness of the metal being cut determines the number of teeth per inch chosen to do the job. There should be no fewer than two or three teeth touching the metal being cut.

Figure 1-2 shows the power hacksaw blade end with a hole for mounting in the machine and the pointed nature of the teeth.



**Figure 1-2** Power hacksaw blade.

### Hacksaw Operation

Straight cuts are made easily on power hacksaws. The vise is stationary, and the cut is made at a right angle to the sides of the stock.

Most machines are equipped with an adjustable vise. Angular cuts at any desired angle up to 45 degrees can be made by swiveling the vise.

To operate the power saw properly, the work should be fastened securely in the vise so that the blade will saw in the proper place. The blade will break if the work loosens in the vise.

The saw blade should be lowered onto the work carefully to start the cut. On some machines this is done by hand, but it can be done automatically on some saws. In either method, the points of the teeth will be broken or damaged if the blade is permitted to strike the work suddenly.

The machine should be watched carefully to make certain that the saw blade lifts about 1/8 inch on the return stroke. If the blade

fails to lift, adjustments should be made immediately, as the blade will be damaged if operation is continued.

When making angular cuts with the work turned at an angle in the vise, another precaution is to be certain that the saw blade can make both the backward and the forward strokes without the saw frame making contact with either the work or the vise. Serious damage to the machine can result from failure to observe this precaution.

When a saw blade is replaced, or a new blade is started in an old cut, it should be remembered that the set of the new blade is wider. The new blade will stick in the old cut unless the work is rotated in the vise a quarter turn. If the work cannot be rotated, the new blade should be guided into the old cut.

The cutting speed of a power hacksaw, of course, varies with the material being cut. Suggested cutting speeds are as follows: for mild steel, 130; for tool steel (annealed), 90; and for tool steel (unannealed), 60. For example, on a machine with a 6-inch stroke, the revolutions per minute of the driving crank should be 130.

All steels should be cut with a cutting compound. Bronze should be cut with a suitable compound at the same speed as mild steel. The saw blade will heat rapidly if an attempt is made to cut brass without a cutting compound adapted to brass. Brass may be cut at the same speed as steel if a suitable compound is used.

### **Power Band Saws**

In the past few years the power band saw has become very important in machine shop operations. In some instances it is used in production operations prior to final machining operations.

#### **Basic Construction**

Power band saws are also designed to make the sawing of metal a mechanical operation (Figure 1-3). The stock can be held in a vise mounted on the machine or it can be supported by the operator's hand. Electric motors are used to supply the power for the band saws.


#### **Drive Mechanism**

Wheels on the power band saw can be adjusted to apply tension to the band saw blade, which is a flexible, thin, narrow ribbon of steel. One of these wheels is powered by the electric motor mounted on the machine. These wheels are enclosed by guards for safety in operation.

#### **Frame**

Many variations of power band saws are available. However, band saws can be grouped into three classifications: horizontal machines for cut-off sawing, vertical machines for straight and profile sawing





**Figure I-3** A power band saw. (Courtesy Kalamazoo Saw Div., KTS Industries.)

at conventional speeds, and vertical machines for nonferrous cutting and friction cutting.

#### **Worktable and Vise**

Power band saws have either a worktable or vise to hold the metal that is to be cut. The worktable is usually part of the band saw. The vise, if there is one, is usually designed to fit the worktable. Many worktables also have T-slots for the purpose of supporting special clamping devices to hold the work to be cut.

#### **Special Features**

Some power band saws have automatic tensioning devices so that the proper amount of tension is applied to the band saw at all times. This type of device reduces excessive wear and damage to the blade.

#### **Coolant System**

Coolant systems are common on power band saws designed for high-speed production work. These systems deliver coolant to the

band saw blade and the work. After the coolant has been used, it is recycled through a screen and filter to remove any chips.

### Capacity of Power Band Saws


The maximum capacity of power band saws varies according to the size of the band saw. Some of the larger machines can accommodate work that is 18" × 18" and larger. Band saws also have the capacity to do a wide variety of operations that include cut-off, straight sawing, and contour, or profile, sawing. Rough shaping and semifinishing can be accomplished on almost all types of ferrous and nonferrous materials.

### Blades

The development of the heavy-duty band saw machine tool has been designed and built to operate with high-speed blades at maximum efficiency. Use of the band saw offers several important advantages over the hacksaw. These advantages include a narrower kerf, which results in greatly reduced losses; fast, efficient cutting with low per-cut costs; and consistently smooth, accurate cutting.



(A) Standard or regular tooth.



(B) Skip tooth.



(C) Hook tooth.

**Figure 1-4** Three tooth styles for blades.

The type of blade used on the power band saw is very important. Blades are available with many different types of teeth, tooth set, and pitch.


The three types of teeth are the regular tooth, skip tooth, and hook tooth (Figure 1-4). The regular tooth blade provides from 3 to 32 teeth per square inch. Teeth may be raker set or wavy set. Regular tooth blades are preferred for all ferrous metals and for general-purpose cutting.

Skip-tooth blades feature widely spaced teeth (usually from 2 to 6 TPI) to provide the added chip clearance needed for cutting softer materials. Teeth of the skip-tooth blade are characterized by straight 90° faces and by the sharp angles at the junction of the tooth and gullet. Since these sharp angles and flat surfaces tend to break up chips, this type of tooth is preferred for the very soft nonferrous metals that would otherwise tend to clog and gum the blade. This blade is also widely used in woodcutting.

Hook-tooth blades provide the same wide tooth spacing as the skip-tooth blade. The teeth themselves have a 10° undercut face. Gullets are deeper with blended radii between the teeth and the

gullets. Since the undercut face helps the teeth dig in and take a good cut, the blended radii tend to curl the chips. This type of tooth is preferred for the harder nonferrous alloys and many plastic operations.

There are three basic types of tooth set on metal-cutting band saw blades. Each tooth set is designed for a specific type of cutting application. These three basic types of tooth sets are the raker set, the wavy set, and the alternate set. See Figure 1-5.



**Figure 1-5** Types of tooth sets for blades.

The raker set—one tooth set left, one tooth set right, and one tooth not set—is preferred for all long cutting runs where the type of material and the size and shape of the work remain relatively constant. It is also for all contour, or profile, cutting applications and for band sawing with high-speed steel blades.

The wavy-set blade, a rolled set with alternate left and right waves, provides greater chip clearance and a stronger, nearly rip-proof tooth. This blade is preferred for general-purpose work on conventional horizontal machines.

The alternate set has every tooth set—one to the left, one to the right—throughout the blade. Taken originally from the carpenter handsaw, it was supplied in band saws for brass foundry applications.


### **Band Saw Operation**

When operating a band saw, there are some general principles that should be followed so that you will be able to select the blade with the proper pitch:


- Small and thin-wall sections of metal require fine teeth.
- Large metal sections require the use of blades with coarse teeth so that adequate chip clearance is provided.

- Two teeth should be engaged in the metal to be cut at all times.
- Soft, easily machined metals require slightly coarser teeth to provide chip clearance. Hard metals of low machinability require finer teeth so that there are more cutting edges per inch.
- Stainless steel should be sawed with a coarse (NQ) tooth saw blade for best results.

Figure 1-6 shows tooth pitches.



(A) Correct and incorrect tooth pitches.




(B) How determined.

**Figure 1-6** Tooth pitches.

Select the widest blade that your machine will accommodate when straight, accurate cutting is required. Blade widths for contour sawing depend upon the specific application.

Profile (or contour) sawing is an accurate, fast, and efficient method of producing complex contours in almost any machinable metal. With the proper blade selection, radii as small as  $\frac{1}{16}$  inch can be cut. Either internal or external contours can be sawed. If an internal contour has to be sawed, it is first necessary to drill a hole within the contour area to accommodate the saw blade. The band saw blade has to be cut to length, threaded through the drilled hole, and then rewelded. It is for this reason that band saws designed and built for contour sawing have a built-in butt welder. Blades for profile sawing are always raker set because this type of tooth provides



**Figure 1-7** Bandwidth selection for profile or contour sawing.

the necessary side clearance. These blades are usually narrower than those chosen for straight cutting; the extra width for any specific job depends upon the smallest radius to be cut. Figure 1-7 will aid you in selecting the correct blade for any application.

Profile sawing requires cutting and rewelding the blade. Because of this, it is necessary to make a good weld. This can be accomplished very easily if certain steps are followed. The steps are as follows:

1. Square both ends of the blade accurately.
2. Align both ends of the blade so that they join evenly across the entire width of the blade.
3. Select the correct dial setting for the blade width.
4. Select the correct annealing period.
5. Dress the blade to remove the welding flash.
6. Anneal for stress relieving.

With the exception of cast iron, coolant should be used for all band-sawing operations. Cast iron is always cut dry. Almost all of the commercially available soluble oils or light cutting oils will give good results when cutting ferrous metals. When aluminum is cut, paraffin and beeswax are commonly used lubricants.

The recommendations shown in Table 1-1 are based on four types of cutting fluids:

- A. *Cutting oil mineral base with fatty oils added* (has sulfur for antiweld characteristics and chlorine for film strength)
- B. *Cutting oil with light viscosity fatty oils* (for cold-weather operations, mix with (A); when cutting copper alloys, additives and chlorine should be added)
- C. *Synthetic water-soluble cutting agent*
- D. *Soluble oil cutting agent with fatty oils* (sulfurized for extreme pressure with antiweldment properties; water-soluble for greater heat removal)

**Table 1-1 Recommended Cutting Fluids**

<b>Materials to Be Cut—Cutting Fluids Recommended</b>						
<b>Operation</b>	<b>Free-Cutting</b>	<b>Alloy</b>	<b>Stainless</b>		<b>Aluminum</b>	
	<b>Steels;</b>	<b>Steels;</b>	<b>Steels</b>	<b>Stainless</b>	<b>Alloys;</b>	<b>Alloys;</b>
	<b>Carbon</b>	<b>Nickel</b>	<b>(Free</b>	<b>(Austenitic);</b>	<b>Leaded</b>	<b>Brass;</b>
	<b>Steels; Cast</b>	<b>Steel;</b>	<b>Cutting);</b>	<b>Manganese</b>	<b>Brass; Gun</b>	<b>Brass;</b>
	<b>Steels;</b>	<b>Nickel-</b>	<b>Ingot</b>	<b>Steels;</b>	<b>Alloys; Metal;</b>	<b>Nickel;</b>
	<b>Malleable</b>	<b>Chromium</b>	<b>Iron;</b>	<b>High-Temp</b>	<b>Phosphor</b>	<b>Nickel;</b>
	<b>Iron</b>	<b>Steel</b>	<b>Wrought</b>	<b>Alloys</b>	<b>Zinc</b>	<b>Inconel</b>
Production sawing using MARVEL high-speed steel, high-speed-edge, and intermediate alloy steel band blades	FLOOD	FLOOD	FLOOD	FLOOD	FLOOD	FLOOD
	(B)	(A)	(A)	(A)	(B)	(A)
	(C) Mix 1 to 5 with water.	(C) Mix 1 to 5 with water.	(D) Mix 1 to 5 with water.	(C) Mix 1 to 5 with water.		(C) Mix 1 to 5 with water.
	(D) Mix 1 to 5 with water.	(D) Mix 1 to 5 with water.	(C) Mix 1 to 5 with water.	(D) Mix 1 to 5 with water.		(D) Mix 1 to 5 with water.

**Table I-1 (continued)**

Operation	Materials to Be Cut—Cutting Fluids Recommended					
	Free-Cutting Steels; Carbon Steels; Cast Steels; Malleable Iron	Alloy Steels; Nickel Steel; Chromium Steel	Stainless Steels (Free Cutting); Ingot Iron	Stainless (Austenitic); Manganese Steels; High-Temp Alloys	Aluminum Alloys; Leaded Brass; Magnesium Alloys; Phosphor Bronze; Zinc	Gun Metal; Nickel; Monel; Inconel
General sawing using MARVEL hard-back & flexible-back hardened-edge band blades	DRIP (blade just wet)	DRIP (blade just wet)	DRIP (blade just wet)	DRIP (blade just wet)	DRIP (blade just wet)	DRIP (blade just wet)
	(B)	(B)	(B)	(A)	(B)	(A)
	(D)	(D)	(D)	(B)	Paraffin dry	(B)
Contour sawing using MARVEL high-speed-edge or hard-back & flexible-back carbon blades	SPRAY OR DRIP	SPRAY OR DRIP	SPRAY OR DRIP	FLOOD OR DRIP	FLOOD	
	(C)	(C)	(C)	(D) Mix 1 to 10 with water.	(B)	(B)
	(D) Mix 1 to 10 with water.	(D) Mix 1 to 10 with water	(D) Mix 1 to 10 with water.	(C) Mix 1 to 10 with water.	Paraffin dry	(A)
			(B)	(A)		

Courtesy Armstrong-Blum Mfg. Co.

The three types of feeds used on power band saws are hand, hydraulic, and mechanical. The number of factors involved in the efficient and trouble-free operation of a power band saw make it difficult to provide specific information on the proper speed or pressure required (see Table 1-2). When a cut is started, the blade should not be forced. If the work is forced into the blade, it will result in a shorter blade life and defective work. The following principles should be used as a guide in selecting the proper feed pressure:

- Use moderate feed pressure when straight, accurate cutting is desired.
- Avoid heavy feed pressures because they will cause the power band saw to chatter and vibrate.
- Study the chips produced. Fine powdery chips indicate the feed is too light. The teeth on the blade are rubbing over the surface of the work instead of cutting the work. Discolored, blued, or straw-colored chips indicate that there is too much feed pressure. This excess pressure can cause teeth to chip and break. In addition, the blade will wear prematurely because of overheating. A free-cut curl indicates ideal feed pressure with the fastest time and the longest blade life.

**Table 1-2 Common Band Sawing Problems and Their Connections**

<b>Problem</b>	<b>Cause</b>	<b>Correction</b>
Blade develops camber.	Roller guides not correctly adjusted.	Readjust.
	Feeding pressure is too heavy.	Use lighter feed.
	Saw guides too far apart.	Adjust closer to work.
Blade develops twist.	Blade riding against flange on metal wheel.	Tilt wheel for proper blade position.
	Saw is binding in cut.	Decrease feeding pressure.
	Side inserts or rollers of saw guides too close to saw.	Readjust.
	Wrong width of blade for radius being cut.	Check for correct blade width.



---

sample content of Audel Machine Shop Tools and Operations

- [Optimist's Tour of the Future online](#)
- [Ancillary Justice \(Imperial Radch, Book 1\) pdf, azw \(kindle\), epub](#)
- [Antisemitism: A Very Short Introduction \(Very Short Introductions\) pdf, azw \(kindle\), epub](#)
- [download online Ask Wendy online](#)
  
- <http://redbuffalodesign.com/ebooks/Optimist-s-Tour-of-the-Future.pdf>
- <http://diy-chirol.com/lib/50-Battles-That-Changed-the-World.pdf>
- <http://drmurphreesnewsletters.com/library/Bitter-Remedy--An-Alec-Blume-Case--Commissario-Alec-Blume-Book-5-.pdf>
- <http://honareavalmusic.com/?books/Cnall-effecten-in-Casablanca.pdf>